

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022822**Date Inspected:** 07-Apr-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li yan hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed.

BAY#19

FCAW welding of weld is identified as 3G-091 of SA6529-001 for SA6529. The welder is identified as 062749. ZPMC QC is identified as Mr. Guo xing hui. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2233-ESAB.

FCAW welding of weld is identified as 3G-016 of SA6529-001 for SA6529. The welder is identified as 058792. ZPMC QC is identified as Mr. Guo xing hui. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2233-ESAB.

FCAW welding of weld is identified as 2F-013 of BK025A3-001 for BK25A-001. The welder is identified as 062783. ZPMC QC is identified as Mr. Guo xing hui. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2132-ESAB.

FCAW welding of weld is identified as 2F-002 of BK025A3-001 for BK25A-001. The welder is identified as 062783. ZPMC QC is identified as Mr. Guo xing hui. The welding variables recorded by QC are appeared to comply with the WPS-B-T-2132-ESAB.

ZPMC QC NDT MT personnel performing MT of bike path stringer plate BK25A-001 fillet weld is in progress.

WELDING INSPECTION REPORT



(Continued Page 2 of 3)

ZPMC personnel performing Fit-up of bike path intermediate stiffener is identified as BKX91 is in progress of Bike path BK025A-001. SMAW welder is identified as 202345.

ZPMC QC NDT UT personnel found second time reject able indications on cable bracket is identified as SA6530-001-016.

This QA inspector performed UT 15% of weld areas previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated an UT report for this date. The members are identified as OBG Cable bracket. The weld designations reviewed as follows SA6031-001-039,056,080.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Kumar,Chadra

Quality Assurance Inspector

Reviewed By: Patel,Hiranch

QA Reviewer